


Nice 4000 Swing

Part Diagrams



4300/4500 Arm



This drawing is a representation and should be used for parts reference only.



4000 Swing

Part Diagrams

4300/4500 Chassis with Control Board

Part Name	Part Number	4000 Models
Arm Assembly, 4300/4500	ABOX4SW	all
Board, Control, 1050	1050US	all
Cover, Front	PPD2262	all
Cover, Rear	PPD2263SW	all
Limit Switch	SPLSM00300	all
Limit Switch Cam	SPAMG046A00	all
Lock and Key	SPREG00300	all
Motor Gearbox, 1/2 hp and 1 hp Motors	SPAMG039B00	all
Motor Kit, 1 hp	NAKM001	all
Motor Kit, 1/2 hp	NAKM002	all
Power Supply	NCO-PWRSUP	all
Rain Ring, Plastic Drip	PPD2265R02-4540	all
Switch Box	10055710	all
Toriod Kit	SPEG001A00A	all